



OHIO HISTORIC INVENTORY

Ohio Historic Preservation Office
Ohio Historical Center
Columbus, Ohio 43211

<p>1. No. 158 FRA-1856-70</p> <p>2. County FRANKLIN</p> <p>3. Location of Negatives OHS</p>	<p>4. Present Name(s) MAPLE GROVE UNITED METHODIST CHURCH</p> <p>5. Other Name(s)</p>	<p>1. No. 158</p> <p>2. County FRANKLIN</p> <p>4. Present Name(s) MAPLE GROVE UNITED METHODIST CHURCH</p> <p>5. Other Name(s)</p>
<p>6. Specific Location 7 W. HENDERSON RD.</p>	<p>16. Thematic Category D 20TH CEN. ARCH.</p> <p>17. Date(s) or Period CORNERSTONE 1941</p> <p>18. Style or Design</p> <p>19. Architect or Engineer RALPH ORR</p> <p>20. Contractor or Builder</p> <p>21. Original Use, if apparent CHURCH</p> <p>22. Present Use CHURCH</p> <p>23. Ownership Public <input type="checkbox"/> Private <input checked="" type="checkbox"/></p> <p>24. Owner's Name & Address, if known MAPLE GROVE UNITED METHODIST 7 W. HENDERSON C.O.S.</p> <p>25. Open to Public? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>26. Local Contact Person or Organization NEWTON A. FRITCHLEY.</p> <p>27. Other Surveys in Which Included</p>	<p>28. No. of Stories 1</p> <p>29. Basement? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>30. Foundation Material STONE</p> <p>31. Wall Construction STONE</p> <p>32. Roof Type & Material GABLED / SHINGLE</p> <p>33. No. of Bays Front 8 Side C</p> <p>34. Wall Treatment ROUGH STONE</p> <p>35. Plan Shape IRREG.</p> <p>36. Changes (Explain in #42) Addition <input checked="" type="checkbox"/> Altered <input type="checkbox"/> Moved <input type="checkbox"/></p> <p>37. Condition Interior GOOD Exterior GOOD</p> <p>38. Preservation Underway? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>39. Endangered? By What? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>40. Visible from Public Road? Yes <input checked="" type="checkbox"/> No <input type="checkbox"/></p> <p>41. Distance from and Frontage on Road 35' x 100'</p>
<p>7. City or Town If Rural, Township & Vicinity COLUMBUS</p> <p>8. Site Plan with North Arrow</p>  <p>9. Coordinates Lat. _____ Long. _____ U.T.M. Reference Zone _____ Easting _____ Northing _____</p> <p>10. Site Building <input checked="" type="checkbox"/> Structure Object <input type="checkbox"/></p> <p>11. On National Register? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>12. Is It Eligible? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>13. Part of Estab. Hist. Dist.? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>14. District Potent'l? Yes <input type="checkbox"/> No <input checked="" type="checkbox"/></p> <p>15. Name of Established District</p>	<p>42. Further Description of Important Features CHURCH IS CONSTRUCTED OF LIMESTONE. LIMESTONE IS CUT IN IRREGULAR ROUGH BLOCKS. WINDOWS ARE LEADED STAINED GLASS. THERE IS A ROUND WINDOW ON THE N. END OF THE CHURCH. THE CHURCH IS BUTTRESSED AT THE CORNERS. THERE IS AN EDUCATIONAL UNIT ON THE S.W. SIDE WHICH IS CONSTRUCTED OF BRICK. THE CHAPEL'S CEILING AND MAIN SANCTUARY CEILING ARE CATHEDRAL TYPE WITH OAK BEAMS.</p>	
<p>43. History and Significance CHURCH WAS BUILT IN SECTIONS FIRST SECTION BUILT IN 1941, SECOND SECTION IN 1954. CHURCH WAS FOUNDED IN 1919</p>	<p>44. Description of Environment and Outbuildings LOCATED A MAJOR INTERSECTION. SURROUNDING AREA IS COMMERCIAL ALONG HIGH STREET AND RESIDENTIAL ON HENDERSON.</p>	
<p>45. Sources of Information VISUAL INSPECTION. CORNER STONE CHURCH PERSONNEL.</p>	<p>46. Prepared by HOBBSTETTER</p> <p>47. Organization C.O.S. INV.</p> <p>48. Date 8-27-25</p> <p>49. Revision Date(s)</p>	

